

PAPER • OPEN ACCESS

Indoor air quality (IAQ) in a naval ship after refit program: a time variation analysis

To cite this article: Maryam Zahaba *et al* 2022 *IOP Conf. Ser.: Earth Environ. Sci.* **1013** 012004

View the [article online](#) for updates and enhancements.

You may also like

- [Ventilation requirements and energy aspects: the case of hospitals](#)
Giorgos Panaras, Risofile Gropca and Giannis Papadopoulos
- [THE COSMIC EVOLUTION OF THE METALLICITY DISTRIBUTION OF IONIZED GAS TRACED BY LYMAN LIMIT SYSTEMS](#)
Nicolas Lehner, John M. O'Meara, J. Christopher Howk et al.
- [A New Measurement of the Temperature–density Relation of the IGM from Voigt Profile Fitting](#)
Hector Hiss, Michael Walther, Joseph F. Hennawi et al.



Free the Science Week 2023 April 2–9

Accelerating discovery through
open access!

 www.ecsdl.org [Discover more!](#)

The banner features a dark blue background with a futuristic, glowing blue interface. A hand is shown pointing at a central circular element that contains a white padlock icon, symbolizing open access. The text is in white and light blue, with the ECS logo and website URL in white.

Indoor air quality (IAQ) in a naval ship after refit program: a time variation analysis

Maryam Zahaba¹, Nur Sarah Fatimah Tamsi¹, Sakinah Engliman², Amirul Faiz Kamaruddin^{2,3}, Noor Artika Hassan⁴ and Arman Ariffin⁵

¹Chemistry Department, Kulliyah of Science, International Islamic University Malaysia, 25200 Kuantan, Malaysia

²Biotechnology Engineering Department, Kulliyah of Engineering, International Islamic University Malaysia, 53100 Gombak, Malaysia

³Faculty of Engineering, KD PELANDOK, Royal Malaysian Navy Naval Base, 32100 Lumut, Malaysia

⁴Community Medicine Department, Kulliyah of Medicine, International Islamic University Malaysia, 25200 Kuantan, Malaysia

⁵Eastern Maintenance Overseer Unit - Royal Malaysian Navy, RMN Naval Base, Tg Purun, 87000 W.P. Labuan, Malaysia

Abstract. Refurbishments of the ship's external and internal structures are the main scopes of a refit program. These activities may affect the indoor air quality (IAQ) inside ships and increase the indoor air pollutants (IAP) concentrations onboard. Therefore, continuous IAQ monitoring is needed to determine IAP exposure to the ship's crew. This study evaluates the changes in IAQ conditions inside a naval ship over a two-time interval to determine the effect of compliance with the recommended engineering control measures proposed in the first assessment. Following the standard of the Industry Code of Practice on Indoor Air Quality 2010 (ICOP on IAQ 2010), seven IAQ parameters (temperature, relative humidity (RH), carbon dioxide (CO₂), respirable particulates/particulate matter (PM₁₀), total volatile organic compounds (TVOC), bacterial count, and fungal count) were measured in two assessment phases. The first phase was conducted after the ship completed the refit program, and the second phase began three months later, following the execution of the recommended engineering control measures. According to the findings of this study, all IAQ parameters improved when compared to the first phase assessment. However, some of the readings were still non-compliance with the standards of ICOP on IAQ 2010. In conclusion, the ship's IAQ parameters were improved following the recommended engineering control measures, although more enhanced approaches were required to ensure all parameters complied with the ICOP on IAQ 2010.

Keywords: Indoor air quality (IAQ); Naval ship; Engineering control; Ship refit program.

¹ Corresponding author: maryamzahaba@iium.edu.my



1. Introduction

Air pollutants may cause adverse effects on the environment and health. The adverse effects of indoor air pollutants (IAP) can be more critical than those effects caused by the outside air pollutants [1]. Previous studies have proved that human exposure to the IAP might be two to multiple times, in terms of the numerous harmful IAP concentrations, higher than the outside air pollutants [2]. On the other hand, low IAP concentrations indicate good indoor air quality (IAQ), leading to a positive impact on the health and productivity of the occupants [3].

Moreover, IAQ is an essential component of indoor environmental quality (IEQ) and plays an important role in ensuring a healthy and safe workplace for the workers and occupants, including those crews in ships. Poor IAQ in onboard ships may cause discomfort and health risks to the crews besides causing equipment breakdown [4]. Ships undergo several refitting programs, with major external and internal refurbishment throughout their service life [5]. Activities such as repainting, adding new furnishings, major component overhauls, and redesigning the interior spaces are among the work scopes of the refitting program [6]. These activities may affect the ship's IAQ and increase the concentrations of IAP onboard. Previously published studies are limited to local surveys with localized climate environments and specific ships condition. A study by Österman et al. (2016) explained the effects of IAQ chemical parameters on passenger ferries in temperate climate countries that specifically operate in the same environment and will not adequately represent other vessels [7]. Meanwhile, few authors have been able to draw on any systematic research into this area of studies that conduct specific IAQ research and compare it to local IAQ guidelines [8][9]. Nonetheless, little is known about the IAQ onboard ships in various conditions, and there is an urgent need to address the safety and health-related problems caused by poor IAQ onboard ships. Thus, this study was done to evaluate the changes in IAQ conditions inside a naval ship over a two-time interval to determine the effect of adhering to the recommended engineering control measures proposed in the first assessment.

2. Methodology

2.1 Sampling sites and assessment phases

The first assessment phase was conducted at the end of December 2020, and the second at the beginning of March 2021. During the first assessment, the ship had recently undergone a refitting program, which included repainting, redesigning the interior spaces, installing new furnishings, and changing other major and minor components. At the end of the assessment, several recommendations and engineering control measures were recommended to the crews to improve the IAQ inside the ship. The second assessment phase was conducted in continuity after three months with the execution of the suggestions made in the previous assessment. The sampling points involved the ship's ten compartments, which comprise accommodation and working spaces. Both assessment phases were conducted when the ship was alongside the jetty. The summary of the IAQ assessment's flow is shown in Figure 1:




Figure 1. The flow of IAQ assessments within two-time intervals and recommendations suggested from the first sampling phase to improve IAQ onboard

2.2 Sampling campaign and instrumentation

The IAQ parameters inside the ship compartments were measured following the Industry Code of Practice on Indoor Air Quality 2010 (ICOP on IAQ 2010) by the Department of Occupational Safety and Health [10]. Prior to the sampling activity, a walkthrough inspection was conducted, including the semi-formal meeting, walkthrough observation and occupant's interview and questionnaire administration. This study measured physical and chemical parameters such as temperature ($^{\circ}\text{C}$), relative humidity (RH), and carbon dioxide (CO_2) which were measured using the TSI VelociCalc 9565. Total volatile organic compounds (TVOC) concentrations were measured using the RAE Systems ppbRAE, and respirable particulates/particulate matter (PM_{10}) concentrations were measured using the Kanomax Digital Dust Monitor Model 3443. The eight-hour sampling period was divided into four slots, with a direct reading taken for five minutes intervals within 30 minutes period of sampling duration for each slot.

Besides that, the bacterial and fungal counts were also assessed as biological parameters for the IAQ. The airborne bacteria and fungi were sampled using the PBI International SAS Super IAQ on trypticase soy agar (TSA) for bacteria and malt extract agar (MEA) for fungi. The sampling was conducted in triplicate for a minute at a flow rate of 100 L/m following the National Institute of Safety and Health (NIOSH) Manual Analytical Method (NMAM) 0800 [11].

2.3 Data analysis

The average total bacterial and fungal count was determined by calculating the colony-forming unit per cubic meter (CFU/m^3) from the previous sampling culture media using the formula (1).

$$\text{Total bacterial or fungal count, CFU}/\text{m}^3 = \frac{\text{Total count} \times 1000}{\text{Volume of sampled air}} \quad (1)$$

The 8-hour total weighted average (TWA_8) of the IAQ parameters was calculated to estimate the average readings of the 8-hour exposure in the compartments. The TWA_8 readings were then compared to the acceptable limit from the ICOP on IAQ 2010. Based on the normality test on the sample data, a non-parametric Wilcoxon signed-rank test was used to analyze the comparison of TWA_8 readings for physical and chemical parameters of each ship's compartment between the two phases of assessment.

3. Results and discussions

3.1 Physical parameters

Data in Table 1 shows that the temperature readings during the second assessment phase were significantly reduced in all compartments except electrical room 2 ($Z = -0.715$, $P = 0.475$). However, the temperature drop from the first phase is too low and falls below the standard set by the ICOP on IAQ 2010 (23–26°C). This result can be explained by the fully functional heating, ventilation, and air conditioning (HVAC) system and execution of the testing, adjusting, and balancing (TAB) done by the engineering department as recommended in the first phase assessment. The RH readings in all sampling points show a positive change from the previous assessment as the temperatures drop. As shown in Table 1, all RH levels in the compartments were within the standard's acceptable limit. These factors could explain the relatively good correlation between temperature and RH [12]. In addition, the heating element was set according to the manufacturer's recommendations in order to control the humidity onboard, and the heating setting was adjusted after the first assessment.

Table 1. TWA₈ reading for physical parameters.

Sampling point	Temperature, °C				Relative humidity, %			
	1 st phase	2 nd phase	Z score	p value	1 st phase	2 nd phase	Z score	P-value
Galley	29.1 ± 0.2 ^a	24.8 ± 1.1	-4.293 ^b	< 0.001 ^c	72.3 ± 4.0 ^a	55.0 ± 2.7	-4.286 ^b	< 0.001 ^c
Common room 1	26.7 ± 0.3 ^a	19.3 ± 0.5 ^a	-4.291 ^b	< 0.001 ^c	75.2 ± 2.5 ^a	68.2 ± 2.1	-4.287 ^b	< 0.001 ^c
Officer's cabin 1	25.6 ± 0.6	20.2 ± 0.8 ^a	-4.291 ^b	< 0.001 ^c	73.5 ± 3.8 ^a	61.3 ± 1.5	-4.287 ^b	< 0.001 ^c
Common room 2	26.6 ± 0.3 ^a	20.0 ± 0.4 ^a	-4.294 ^b	< 0.001 ^c	75.2 ± 2.2 ^a	65.4 ± 1.2	-4.286 ^b	< 0.001 ^c
Officer's cabin 2	25.6 ± 0.6	22.6 ± 0.1 ^a	-4.291 ^b	< 0.001 ^c	66.0 ± 4.1	68.3 ± 3.3	-2.029	0.042 ^c
Gym	29.3 ± 0.9 ^a	27.1 ± 1.4 ^a	-4.305 ^b	< 0.001 ^c	72.0 ± 4.2 ^a	57.1 ± 5.2	-4.286 ^b	< 0.001 ^c
Electrical room 1	25.0 ± 1.5	22.7 ± 0.6 ^a	-3.987 ^b	< 0.001 ^c	67.1 ± 7.0	64.0 ± 3.3	-1.958 ^b	0.05
Electrical room 2	19.5 ± 2.3 ^a	21.3 ± 10.4 ^a	-0.715	0.475	69.1 ± 3.4	64.2 ± 4.5	-2.972 ^b	0.003 ^c
Officer's cabin 3	23.9 ± 0.9	21.0 ± 1.0 ^a	-4.299 ^b	< 0.001 ^c	67.9 ± 2.8	66.4 ± 3.0	-2.788 ^b	0.005 ^c
Bridge	25.7 ± 0.6	22.1 ± 1.5 ^a	-4.289 ^b	< 0.001 ^c	70.2 ± 13.3 ^a	64.4 ± 3.1	-2.029 ^b	0.043 ^c

^a Noncompliance reading with ICOP on IAQ 2010

^b 1st phase assessment > 2nd phase assessment

^c Significant different at $P < 0.05$

Table 2. TWA₈ reading for chemical parameters

Sampling point	Carbon dioxide (CO ₂), ppm			Total volatile organic compound (TVOC), ppm			Particulate matter (PM ₁₀), mg/m ³			
	1 st phase	2 nd phase	Z score	1 st phase	2 nd phase	Z score	1 st phase	2 nd phase	Z score	P-value
Galley	890 ± 99	754 ± 36	-3.743 ^b	19.30 ± 10.33 ^a	4.09 ± 0.81 ^a	-4.286 ^b	0.108 ± 0.032	0.007 ± 0.010	-4.258 ^b	< 0.001 ^c
Common room 1	1092 ± 117 ^a	761 ± 97	-4.286 ^b	36.27 ± 24.45 ^a	4.13 ± 0.29 ^a	-4.286 ^b	0.072 ± 0.024	0.002 ± 0.002	-4.287 ^b	< 0.001 ^c
Officer's cabin 1	1229 ± 90 ^a	913 ± 145	-4.143 ^b	12.76 ± 2.9 ^a	2.96 ± 0.18	-4.286 ^b	0.040 ± 0.018	0.004 ± 0.002	-4.287 ^b	< 0.001 ^c
Common room 2	1126 ± 83 ^a	816 ± 81	-4.286 ^b	16.37 ± 3.96 ^a	4.27 ± 0.26 ^a	-4.286 ^b	0.154 ± 0.230 ^a	0.003 ± 0.007	-4.287 ^b	< 0.001 ^c
Officer's cabin 2	1247 ± 328 ^a	713 ± 93	-4.287 ^b	8.70 ± 2.13 ^a	3.27 ± 0.14 ^a	-4.286 ^b	0.314 ± 0.306 ^a	0.002 ± 0.001	-4.288 ^b	< 0.001 ^c
Gym	911 ± 379	781 ± 58	-1.571 ^b	5.03 ± 4.13 ^a	3.50 ± 0.37 ^a	-1.209 ^b	0.235 ± 0.200 ^a	0.004 ± 0.001	-4.287 ^b	< 0.001 ^c
Electrical room 1	2040 ± 404 ^a	977 ± 172	-4.286 ^b	14.19 ± 1.92 ^a	4.02 ± 0.39 ^a	-4.286 ^b	0.035 ± 0.037	0.005 ± 0.005	-4.289 ^b	< 0.001 ^c
Electrical room 2	1008 ± 294 ^a	960 ± 223	-1.243 ^b	4.93 ± 2.02 ^a	3.20 ± 0.16 ^a	-2.4 ^b	0.022 ± 0.045	0.045 ± 0.003	-2.645	0.008 ^c
Officer's cabin 3	1213 ± 203 ^a	987 ± 139	-2.286 ^b	5.14 ± 1.42 ^a	3.42 ± 0.26 ^a	-4.256 ^b	0.022 ± 0.006	0.016 ± 0.008	-3.304 ^b	0.001 ^c
Bridge	1265 ± 169 ^a	828 ± 156	-4.172 ^b	1.47 ± 0.56 ^a	1.79 ± 0.34	-1.743	0.063 ± 0.146	0.004 ± 0.002	-4.287 ^b	< 0.001 ^c

^a Noncompliance readings with ICOP on IAQ 2010

^b 1st phase assessment > 2nd phase assessment

^c Significant different at $P < 0.05$

3.2 Chemical parameters

In the case of chemical parameters, a Wilcoxon signed-rank test in Table 2 shows that the difference in CO₂ concentration between the first and second assessments was statistically significant in all compartments except the gym ($Z = -1.571$, $P = 0.116$) and electrical room 2 ($Z = -1.243$, $P = 0.214$). All compartments improved their ventilation by demonstrating a decreasing CO₂ concentration in the second assessment phase and falling below the acceptable limit set by the ICOP on IAQ standard (< 1000 ppm). The data from the gym and electrical room 2 must be interpreted with caution because the source of the CO₂ during sampling could be human respiration [13]. Overall, the decreasing CO₂ trend could be attributed to the engineering control measures activities conducted by ship crews. To reduce the CO₂ concentration, fresh air must be introduced into the compartment, causing the concentrated IAP to dilute away. According to Fang et al. (2019), forced ventilation is typically used in tunnel construction because it is a cost-effective method to provide large amounts of fresh air. A similar outcome in this study was found to be significant when compared to previous findings [14].

Furthermore, Table 2 shows a statistical difference in TVOC concentration between the first and second assessment in all compartments except the gym ($Z = -1.209$, $P = 0.304$) and the bridge ($Z = -1.743$, $P = 0.081$). Apart from the bridge, all readings showed a decrease in TVOC concentration during the second assessment. All compartments recorded exceeded the value of TVOC during the first assessment due to the major and minor refurbishment activity of the ship, as expected from the refitting program. This is supported by the idea that new furniture, painting, and surrounding materials such as carpets cause TVOC emissions [15]. Despite some inconsistency, the concentrations of TVOC were interestingly reduced from the initial IAQ assessment. Presumably, it was due to routinely flush out activity taken by the crew as recommended in the first assessment. The three months of an activity practice, however, was insufficient to dilute the TVOC emission, as most of the compartments still recorded an exceeding concentration from the acceptable limit as prescribed in the ICOP on IAQ 2010.

The statistical analysis results for PM₁₀, similar to other parameters, show a significant difference in concentration between the first and second phase assessments in all compartments. All readings showed positive feedback from the engineering control measures taken, which routinely flushes out the indoor air. The ship's refurbishment activity indeed increased the concentration of PM₁₀, as seen in the common room 2, officer's cabin 2, and gym during the first assessment. According to studies, renovation and refurbishment activities increase the concentration of PM₁₀ in the surrounding air [16]. Since PM₁₀ can adversely affect the health of the ship's crew, it can be avoided further by employing the individual prevention technique of wearing personal protective equipment (PPE) during the activity. A good practice of wearing appropriate PPE while working in areas with high concentrations of PM₁₀ can reduce the risk of human inhalation of PM₁₀. This corroborates the ideas of Shakya et al. (2017) who investigated the efficacy of facemasks in reducing particulate matter exposure [17].

3.3 Biological parameters

Most compartments reported a decrease in airborne bacterial and fungal count from the first phase assessment to the second assessment, except for fungal count in the bridge. Figures 2 and 3 show the different results for the bioaerosol count between the two phases and demonstrate the efficiency of the decontamination activity and the right setting of humidity controller on the HVAC system as practiced by the crew, by referring to the manufacturer's manual. The refurbishment activity during the refitting program had caused the resuspension of the microorganisms in the air and explained the exceeding CFU for the bacteria and fungi during the first assessment. Mousavi et al. (2020) found that renovation and refurbishment activities increase the resuspension of PM as well as microorganisms since PM can be a potential carrier for the microorganisms [18]. High CFU count of microbial is related to the high concentration of PM [19][20].




Figure 2. Total bacterial count during assessment phases




Figure 3. Total fungal count during assessment phases

4. Conclusions

Overall, this study found that the IAQ parameters improved after a three-month interval of assessment and execution of recommended control measures from the first assessment. The findings demonstrate the effectiveness of activities such as TAB of HVAC system, routinely flushing out the indoor air and decontamination activities, as well as the proper setting of heating elements to control humidity, in reducing IAP concentrations and the dilution process over the months. Even though this study was based on limited samples on a ship, the findings proved that proper maintenance and a high level of awareness of IAQ among the crews onboard would sustain a healthier environment inside the ship. Hence, further studies regarding the IAQ onboard ships would be worthwhile.

5. Acknowledgement

This study would like to thank the International Islamic University of Malaysia (IIUM) and the Royal Malaysian Navy (RMN) for their assistance with this work (grant ID: RMCG20-044-0044). We would like to express our sincere gratitude to the Eastern Maintenance Overseer Unit, RMN, for granting us access to the ship, as well as all of the crews who were involved in the study.

6. References

- [1] Tsakas M P, Siskos A P, Siskos P A 2011 Indoor air pollutants and the impact on human health. *Chemistry, Emission Control, Radioactive Pollution and Indoor Air Quality*, 447-84.
- [2] Maré M, Śmiełowska M, Namieśnik J, Zabiegała B 2018 Indoor air quality of everyday use spaces dedicated to specific purposes—a review. *Environmental Science and Pollution Research*, 25(3), 2065-82.
- [3] Loftness V 2020. Sustainable built environments. Haase D, editor. New York: Springer; 2020.
- [4] Rozzi-ochs J A 2006 *Shipboard Ventilation Systems and Design Standards on Board*
- [5] Liu Y, Frangopol D M and Cheng M 2019 Risk-informed structural repair decision making for service life extension of aging naval ships. *Marine Structures*, 64, 305–321. <https://doi.org/10.1016/j.marstruc.2018.10.008>
- [6] Cruise 2020 *Top 10 cruise ship refit and refurbishments in 2020* <https://cruise-arabia.com/2020/02/14/top-10-cruise-ship-refit-and-refurbishments-in-2020/>
- [7] Österman C, Langer S and Moldanova J 2016 Personal exposure of seafarers to air pollutants and perceived indoor air quality on a passenger ferry. *Indoor Air 2016. The 14th International Conference on Indoor Air Quality and Climate*.
- [8] Langer S, Moldanová J and Österman C 2016 Influence of fuel change on indoor environmental quality on-board a passenger ferry. *The 14th International Conference of Indoor Air Quality and Climate, Ghent, Belgium July 4-8. International Society of Indoor Air Quality and Climate-ISIAQ*
- [9] Carrer P and Wolkoff P 2018 Assessment of indoor air quality problems in office-like environments: Role of occupational health services. *International Journal of Environmental Research and Public Health*, 15(4). <https://doi.org/10.3390/ijerph15040741>
- [10] Department of Safety and Health 2010 *Industry Code of Practice on Indoor Air Quality 2010*. Ministry of Human Resources Malaysia
- [11] Lonon M K 1998 *Bioaerosol sampling (Indoor Air) 0800 Culturable organisms : bacteria , fungi , thermophilic actinomycetes* (Issue 1).
- [12] Pei C. Ou, Q and Pui, D Y H 2021 Effects of temperature and relative humidity on laboratory air filter loading test by hygroscopic salts. *Separation and Purification Technology*, 117679. <https://doi.org/10.1016/j.seppur.2020.117679>
- [13] Andrade A, Dominski F H, Pereira M L, de Liz C M and Buonanno G 2018 Fitness centers demonstrate CO₂ concentration levels above recommended standards. *Acta Scientiarum - Health Sciences*, 40. <https://doi.org/10.4025/actascihealthsci.v40i1.35768>
- [14] Fang Y, Yao Z and Lei S 2019 Air flow and gas dispersion in the forced ventilation of a road tunnel during construction. *Underground Space (China)*, 4(2), 168–179. <https://doi.org/10.1016/j.undsp.2018.07.002>
- [15] Mečiarová L, Vilčeková S, Burdová E K and Kiselák J 2017 Factors effecting the total volatile organic compound (TVOC) concentrations in slovak households. *International Journal of Environmental Research and Public Health*, 14(12). <https://doi.org/10.3390/ijerph14121443>
- [16] Szewczyńska M, Dobrzyńska E, Pośniak M. Determination of phthalates in particulate matter and gaseous phase emitted in indoor air of offices. *Environmental Science and Pollution Research*. 2020 Sep 22:1-9.
- [17] Shakya K M, Noyes A, Kallin R and Peltier R E 2017 Evaluating the efficacy of cloth facemasks in reducing particulate matter exposure. *Journal of Exposure Science and Environmental Epidemiology*, 27(3), 352–357. <https://doi.org/10.1038/jes.2016.42>

- [18] Mousavi E, Sharma V, Gajjar D and Naini S S 2020 Renovation in hospitals: a case study on the use of control cubes for local repairs in health-care facilities. *Journal of Facilities Management*.
- [19] Khamal R, Isa Z M, Sutan R, Noraini N M R and Ghaz H F 2019 Indoor particulate matters, microbial count assessments, and wheezing symptoms among toddlers in urban day care centers in the district of seremban, Malaysia. *Annals of Global Health*, 85(1), 1–12. <https://doi.org/10.5334/aogh.2425>
- [20] Morakinyo O M, Mokgobu M I, Mukhola M S and Godobedzha T 2019 Biological composition of respirable particulate matter in an industrial vicinity in South Africa. *International Journal of Environmental Research and Public Health*, 16(4). <https://doi.org/10.3390/ijerph16040629>